

Company Name



2012 Post Roof Maintenance Report


Design Systems Builders, Inc.
1332 Murfreesboro Road
Nashville, TN 37217

ITEMS ADDRESSED/ REPAIRED

Inspection Item	Acceptable	Roof Repair	Suggested Repair Actions
Fasteners	yes	Replaced 50 screws	
Panel end Laps	good	replaced 20 screws	
Ridge Assembly	na		
Gable Trim	good		
Eave Trim	na		
Parallel Flashing	good		
Perpendicluar Flashing	na		
Parapet (in-wall) Gutter	na		
Valley Flashings	na		
Hip Flashing	na		
Skylights	na		
Pipe Penetrations	good		
Exhasut Fan Curbs	na		
Mechanical Curbs	na		
Roof Slope Step Flashing	na		

Roof Plan Sketch

Sketch roof plan below and indicate areas requiring corrective measures. (Copy of original project roof plan with notations may be used in lieu of this sketch.)



General correction/repair notes:



08/28/2012



08/28/2012





